


WYNDWOOD PLACE SUBDIVISION



GEORGE BUTLER ASSOCIATES, INC.
Engineers / Architects / Landscape Architects / Planners

PROJECT	SHEET NO.	TOTAL SHEETS
WESTBROOK STORM DRAINAGE IMPROVEMENTS	2	3
PROJECT NO.: 7137	DATE: JULY, 1994	
REVISIONS:		



GENERAL NOTES

- All disturbed grass areas are to be sodded to match existing type and color. The cost for sod shall be subsidiary to other items.
- Any additional material and labor costs for the connection to Existing Area Inlet No. 6 shall be subsidiary to other items. The connection shall be approved by the Engineer.
- Remove and replace chainlink fence as required. Temporary fencing shall be installed during construction in lieu of permanent fencing. Costs shall be subsidiary to other items.
- Remove and replace sprinklers as required. Costs shall be subsidiary to other items.
- All disturbed landscaped areas are to be landscaped to match adjacent landscaped areas. The cost for landscaping shall be subsidiary to other costs.
- Contractor is to regrade areas to allow consistent positive drainage as shown on the plan. Cost for grading shall be subsidiary to other costs.
- Pavement is to be saw cut and replaced with 6 inches P.C.C. with 18 inch No. 5 rebar drilled into existing pavement spaced at 30 inch centers.
- Contractor is to maintain one lane of Westbrook Drive open at all times during construction.

NOTE:

Existing underground and overhead utilities and drainage structures have been plotted from available information and their locations must be considered approximate only. It is the responsibility of the contractor to notify the utility companies and to verify the locations of existing utilities before actual construction begins. Any discrepancies noted must be reported to the Engineer immediately.

SCALE: 1" = 20'

WESTBROOK MANOR SUBDIVISION

