

GENERAL NOTES:

- INSTALL AND LOCATE DEVICES IN ACCORDANCE WITH THE 1996 BOCA NATIONAL BUILDING CODE, NFPA 72 AND NFPA 70.
- WHERE POWER BOOSTER ARE REQUIRED, CONNECT TO NEAREST 120V/1 CIRCUIT FOR POWER.
- REFER TO ELECTRICAL AND ARCHITECTURAL DRAWING FOR LOCATION OF DOOR HOLDERS AS WELL AS DOOR LOCK RELEASES.
- 4. SECURITY CAMERAS TO BE WIRED BACK TO MONITOR IN COMMUNICATION ROOM 2ND FLOOR EAST WING CAMERAS #11 through #20 SHALL BE ON SEPARATE MONITOR.

Date SEPT. 4, 1997

CONSTRUCTION **DOCUMENTS**

Campbell,

CONSTRUCTION ISSUE DECEMBER 5, 1997

CHANGE ORDER NO. 1 JANUARY 27, 1998