



THIS BEARING LISTED AS S88°36'00"W ON RECORD AT. THIS CAUSES A MATHEMATICAL MIS-CLOSURE OF 64'. A BEARING OF S88°36'00"E WAS USED WHICH REATES A CLOSED FIGURE.

*the wall in discrepancy*