

NOTE: ALL SANITARY LATERALS AND SANITARY MAINS CROSSING UNDER PAVEMENT MUST HAVE PROPER ROCK BACKFILL AND REQUIRED COMPACTION.


- DCSD NOTES:**
- EXISTING SANITARY SEWER SERVICE SHALL NOT BE INTERRUPTED
 - MODIFY INVERTS TO DRAIN PROPERLY
 - INSTALLATION OF SANITARY SEWER MAINS REQUIRES DCSD INSPECTION. CONTACT STEVE OVERBEY, DCSD CHIEF INSPECTOR, AT 363-441-1244 TO SCHEDULE INSPECTION. 48 HOUR ADVANCE NOTICE IS REQUIRED.

SCALE: 1" = 50' HORIZ.
1" = 10' VERT.

| NO. | DATE | REVISION DESCRIPTION |
|-----|---------|-----------------------------|
| 3 | 5/21/14 | CITY COMMENTS |
| 2 | 5/07/14 | CITY, DCSD & WATER COMMENTS |
| 1 | 3/26/14 | DCSD COMMENTS |

DEVELOPER/OWNER:
PULTE GROUP
 17107 CHESTERFIELD AIRPORT RD, STE 120
 CHESTERFIELD, MO 63005
 PHONE: (636) 537-7129

THE PROFESSIONAL ENGINEER'S SEAL APPEAR HEREON ASSUMES RESPONSIBILITY ONLY FOR WHAT APPEARS ON THIS PAGE, AND DISCLAIMS RESPONSIBILITY FOR ANY OTHER PARTS OF THE PROJECT. THIS SEAL IS VALID ONLY FOR THE PROJECT TO WHICH IT IS APPLIED. IT IS VOID FOR ANY PART OR PARTS OF THE PROJECT TO WHICH THIS SEAL REFERS.



PRESTON WOODS PHASE 7 IMPROVEMENT PLANS
 PRESTON WOODS LANE
 O'FALLON, MO 63366

SANITARY PROFILES

ST. CHARLES
 1520 S. Fifth Street
 Suite 307
 St. Charles, MO 63303
 636.978.7508

COLE
 CIVIL ENGINEERING / SURVEYING / PLANNING / LANDSCAPE ARCHITECTURE
 Cole & Associates, Inc.

| | |
|----------------|------------|
| DESIGN/CALC BY | MTS |
| DRAWN BY | MTS |
| CHECKED BY | JFH |
| DRAWING SCALE | |
| DATE | 01/07/2013 |
| Job Number | 13-0109 |
| Sheet Number | C7.1 |

DATE: May 23, 2014 - 2:25:08 PM
 DRAWING: S:\Projects\13-0109\13-0109\DCSD-DWG\13-0109-C7.1.dwg
 C:\Users\joverbey\OneDrive\Documents\13-0109-C7.1.dwg