



NOTE: ALL SANITARY LATERALS AND SANITARY MAINS CROSSING UNDER PAVEMENT MUST HAVE PROPER ROCK BACKFILL AND REQUIRED COMPACTION.

**DSCD NOTES:**

- EXISTING SANITARY SEWER SERVICE SHALL NOT BE INTERRUPTED
- MODIFY INVERTS TO DRAIN PROPERLY
- INSTALLATION OF SANITARY SEWER MAINS REQUIRES DSCD INSPECTION. CONTACT STEVE OVERBEY, DSCD CHIEF INSPECTOR, AT 363-441-1244 TO SCHEDULE INSPECTION. 48 HOUR ADVANCE NOTICE IS REQUIRED.

SCALE: 1" = 50' HORIZ.  
1" = 10' VERT.

USER: Taylor, Stuart; TAB: Sanitary (2)  
DATE: May 22, 2014 - 2:17:22 PM  
DRAWING: S:\085\0852013\13-0108\CSD-DMV\C-04\IP-RWSE7\CLIP\_PLOT\_PROFILES.dwg

NO	DATE	REVISION DESCRIPTION
1	3/27/13	CITY COMMENTS
2	3/27/13	CITY COMMENTS
3	3/27/13	CITY COMMENTS

DEVELOPER/OWNER:  
**PULTE GROUP**  
1707 CHESTERFIELD AIRPORT RD, STE 120  
CHESTERFIELD, MO 63005  
PHONE: (636) 537-7129

CIVIL ENGINEERS  
CORPORATE  
CERTIFICATE  
#01165

JOHN F. HARBARGER  
REGISTERED PROFESSIONAL ENGINEER  
NO. E-29716  
DATE: 3/27/13

**PRESTON WOODS  
PHASE 7  
IMPROVEMENT PLANS**  
PRESTON WOODS LANE  
O'FALLON, MO 63366

**SANITARY PROFILES**

**ST. CHARLES**  
1520 S. Fifth Street  
Suite 307  
St. Charles, MO 63303  
636.978.2508 fax

**COLE**  
CIVIL ENGINEERING / SURVEYING / PLANNING / LANDSCAPE ARCHITECTURE  
Cole & Associates, Inc.

DESIGN/CALC BY	MTS
DRAWN BY	MTS
CHECKED BY	JFH
DRAWING SCALE	-
DATE	01/07/2013
Job Number	13-0109
Sheet Number	C7.2