


BMP TABLE (NORTH DITCH TRIBUTARY AREA)

BMP AREA	TRIBUTARY AREA	BMP	WATER QUALITY VOLUME REQUIRED	WATER QUALITY VOLUME PROVIDED	PERVIOUS PAVEMENT AREA	TRIBUTARY IMPERVIOUS AREA TO PERVIOUS PAVEMENT	RATIO
1	0.28 ACRES	FRENCH DRAIN	826 C.F.	856 C.F.	N/A	N/A	N/A
2	0.19 ACRES	PERVIOUS CONCRETE	N/A	N/A	3,663 S.F.	8,179 S.F.	2.2:1
3	0.11 ACRES	PERVIOUS CONCRETE	N/A	N/A	1,425 S.F.	8,399 S.F.	5.8:1
BYPASS#1	0.16 ACRES	UNTREATED, DISTURBED	53 C.F.	0 C.F.	N/A	N/A	N/A
BYPASS#2	0.08 ACRES	UNTREATED, DISTURBED	444 C.F.	0 C.F.	N/A	N/A	N/A
BYPASS#3	0.38 ACRES	UNTREATED, DISTURBED	618 C.F.	0 C.F.	N/A	N/A	N/A



PAUL K. BOYER, P.E. E-28258
CIVIL ENGINEER
CEDC LICENSE NO.: 2003004674

DESCRIPTION:

PROGRESS SET	8-31-18
PERMIT SET	10-5-18
CITY SUBMITTAL	10-30-18
CITY RESUBMITTAL	11-27-18

Issue Date:	10-5-18
Job Number:	1823
Drawn By:	PKB
Checked By:	PKB
Drawing Title:	

Best Management Practices Plan